## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,811,472 B2

Page 1 of 1

**DATED** 

: November 2, 2004

INVENTOR(S) : Tran et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 12,

Lines 35 and 52, "tapping" should read -- lapping --.

Lines 61 and 63, "stands" should read -- strands --.

## Column 13,

Line 7, "stands, wherein to" should read -- strands, wherein the --.

Line 9, "unit" should read -- units --.

Lines 15, 18 and 42, "stands" should read -- strands --.

Line 47, "apposite" should read -- opposite --.

## Column 14,

Line 12, "stands" should read -- strands --.

Line 54, "wow" should read -- narrow --.

Line 57, "mechanisms" should read -- magnetic clutch mechanisms --.

Signed and Sealed this

Fifth Day of July, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office